




# Guadalupe St. Storm Drain Improvements

## Architectural Review Committee


Kim Patak, PE, CFM, ENV SP



# PROJECT BACKGROUND




# PRE-PROJECT INUNDATION – 100 YR






# POST PROJECT INUNDATION – 2 YR




# POST PROJECT INUNDATION – 10 YR






# POST PROJECT INUNDATION – 25 YR



# POST PROJECT INUNDATION – 100-YR





# EXISTING CROSSING AT W. 33RD





# EXISTING CROSSING AT W. 33RD





# FLOODING DAMAGE






# PROPOSED CROSSING

“repair or in-kind replacement of deteriorated historic fabric will most often meet compatibility goals. Compatible alterations will not outweigh the visual impact of the original design, nor obscure the resource’s character-defining features, nor add conjectural details”


“Repairs to existing features must maintain historic materials and character of the feature”



# PROPOSED CROSSING



# PROPOSED CROSSING





# Questions?

**Kim Patak, P.E., CFM, ENV SP**

**Consultant Project Manager**

**kkp@freese.com**

**(512) 617-3138**

**Rebeka McKay, P.E., CFM**

**WPD Project Sponsor**

**rebeka.mckay@austintexas.gov**

**(512) 974-3353**

**David Hernandez, P.E.**

**PWD Project Manager**

**david.hernandez3@austintexas.gov**

**(512) 974-3014**



INNOVATIVE APPROACHES... PRACTICAL RESULTS... OUTSTANDING SERVICE